## ST CATHERINE ELEMENTARY SCHOOL CALGARY, ALBERTA

School Facility Evaluation Project Calgary Roman Catholic Separate School South Region, District #1

> Prepared For Alberta Infrastructure March 2000

Prepared By
Bathory Associates Architecture + Interior Design— Architectural
Wiebe Forest Engineering Ltd. – Mech. & Elect.

## **TABLE OF CONTENTS**

	Page
Executive Summary	i
Facility Profile and Summary	1
Section 1 – Site Conditions	4
Section 2 – Building Exterior	7
Section 3 – Building Interior	11
Section 4 – Mechanical Systems	14
Section 5 – Electrical Systems	21
Section 6 – Portable Buildings	26
Section 7 – Space Adequacy	27
Mini Plans	Ai
Typical Photographs	Aiii

# **Evaluation Team** Architectural

Bathory Associates Architecture + Interior Design Suite 200, 1333 – 8<sup>th</sup> St SW Calgary, Alberta, T2R 1M6

Phone: 403 229 9222 Fax: 403 228 0882

Email: cba.dwgfiles@home.com

Mechanical

Wiebe Forest Engineering Ltd

4040 Bowness Road
Calgary, Alberta, T3B 3R7
Phone: 403 670 7300
Fax: 403 670 7301
Email general@wfe.ab.ca

Electrical

**Wiebe Forest Engineering Ltd** 

4040 Bowness Road Calgary, Alberta, T3B 3R7 Phone: 403 670 7300 Fax: 403 670 7301 Email general@wfe.ab.ca

## **EXECUTIVE SUMMARY**

In March 2000 Alberta Infrastructure engaged Bathory Associates Architecture + Interior Design to evaluate the condition of nineteen schools within the Calgary Roman Catholic Separate School District. A standardized form, developed by Alberta Infrastructure and supplied to the evaluation team by the regional coordinator was used to document the condition and recommendations.

The original building was constructed in 1971. The facility currently has four portables on site. The original open plan has been subdivided into classrooms and library. The ancillary off the stage has been subdivided into a computer room and a resource room. New floor finishes have been installed.

The school is constructed of concrete slab on grade, masonry bearing wall and steel columns. The roof structure is wood deck on steel and wood structure.

## **Summary of Observations and Recommendations**

The school jurisdiction has a roof replacement program in place and consequently the roofing for all schools within the jurisdiction is generally not a deficiency. The presence of hazardous material in the building is not expected, but should be evaluated before any major renovation work is undertaken.

#### Architectural

The building is in good condition. Some replacement of operating sash and minor work to accommodate the recommended mechanical and electrical renovations is required.

#### Mechanical

The systems are in reasonable condition, however, controls and zoning are required to reflect the subdivided layout to provide adequate heat and ventilation.

#### Electrical

The electrical systems are in fair condition. The main service panels and distribution panels require upgrading. The electrical distribution is inadequate and requires additional outlets and surge protection for program and convenience. Lighting is generally original and also requires replacement.

## Costing

The estimated construction costs for the remedial work in the attached evaluation form has been based on the Costing Unit Rate Chart developed by Alberta Infrastructure. Where this data was incomplete or inappropriate to the recommended work, unit costs based on the local Calgary market were used.

1.	Site Related Work	\$0.00
2.	Building Exterior	\$18,700.00
3.	Building Interior	\$80,000.00
4.	Mechanical Systems	\$15,500.00
5.	Electrical Systems	\$57,000.00
6.	Portables	\$14,500.00
	Total Estimated Costs	\$185,700.00

## Space Adequacy

The existing area, according to the <u>School Building Area Guidelines</u> and <u>Supplement - Maximum Gross Area of School</u> Building Projects is deficient.

Existing Total Gross Area (sm)	2196
Projected required total gross area (sm)	2485
Overage / (deficiency) (sm)	(289)

## Further Investigation

Further investigation is required to assess the impact of the removal of hazardous material during any renovation work.

## School Plan Data Information

The plan information for the building was supplied by Alberta Infrastructure. Area information was extrapolated from the plans. The information does not reflect the current plan.