School Facility Evaluation Project Part II - Physical Condition

Hillcrest Community School March 15, 2000

| School Name: | Hillcrest Community School | School Code: | | 1712 |
|---------------|----------------------------|------------------|-------------------|------|
| Location: | Blumenort, Alberta | Facility Code: | | 558 |
| Region: | North | Superindendent: | Michael Davenport | |
| Jurisdiction: | Fort Vermilion SD No. 52 | Contact Person: | Dan Dyck | |
| | | Telephone: | (780) 927 3766 | |
| Grades: | K-IX | School Capacity: | 275 | |

| Building Section | Year of Compl. | No. of Floors | Gross Bldg Area (Sq.M.) | Type of Construction (i.e., structure, roof, cladding) | Description of Mechanical Systems (incl. major upgrades) | Comments/Notes |
|-------------------|----------------|------------------|----------------------------|--|--|-----------------|
| Original Building | 1985 | | | | Central hydronic heating and | Good condition. |
| | | | | steel roof structure. | central air handling units. | |
| Additions/ | | | | | | |
| Expansions | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| 1 | | | | | | |
| ĺ | | | | | | |

Evaluator's Name: & Company:

Vivian Manasc, MRAIC, MBA
Manasc Isaac Architects Ltd.

| Upgrading/ Modernization (identify whether minor or major) | | | | | |
|--|----------|------------|-----------------|--|--|
| Portable Struct. (identify whether attached/perman. or free-standing/ relocatable) | 1987 | | | 2 wood frame portable classrooms and corridor. | |
| List of Reports/ Supplementary Information | Roof Rep | oort, Albe | rta Independent | t, October 1997. | |

| Evaluation Components | Summary Assessment | р |
|--|---|---------------|
| 1 Site Conditions | Large, well landscaped site. Remove underground fuel storage tank. | \$ 30,000.00 |
| 2 Building Exterior | New brick finish, BUR roof in good condition but requires on-going repairs. Operable windows are required in selected areas. Skylights require on-going repair and should be replaced with clerestorey's. | \$ 120,000.00 |
| 3 Building Interior | All finishes in good condition. | \$ 40,000.00 |
| 4 Mechanical Systems | The mechanical systems, installed in 1984, appear to meet the current standards for school design. Further investigation is required to determine if the water supply available for fire protection meets current code. Due to the area covered by the School Division, a DDC Control System would greatly enhance the operation and maintenance of the mechanical systems. | \$ - |
| 5 Electrical Systems | The electrical systems are well maintained and in good condition. The electrical power distribution system meets current school requirements and can be easily expanded to meet future expansion. The lighting systems are adequate and meet accepted standards for lighting levels. An energy conservation retrofit of the lighting systems would realize a two year payback. The fire alarm system equipment is obsolete and does not have any visual signal appliances. (strobes). Communication | \$ 44,000.00 |
| 6 Portable Buildings | Two portables in aging condition. Two of the furnaces are in need of replacement. | \$ 30,000.00 |
| 7 Space Adequacy: | | |
| 7.1 Classrooms | Classrooms are somewhat small but adequate given the small class sizes. | |
| 7.2 Science Rooms/Labs | | |
| 7.3 Ancillary Areas | Combined art/science room. | |
| 7.4 Gymnasium | Gym is well suited to school needs. | |
| 7.5 Library/Resource Areas | | |
| 7.6 Administration/Staff Areas | Sufficient space for present staff. | |
| 7.7 CTS Areas | | |
| 7.8 Other Non-Instructional Areas (incl. gross-up) | | |

School Facility Evaluation Project Part II - Physical Condition

Hillcrest Community School March 15, 2000

| Evaluation Components | Summary Assessment | р |
|--|--------------------|---------------|
| Overall School Conditions & Estim. Costs | | \$ 264,000.00 |

| Cootion 4 | loite conditions | Rating | Comments/Concerns | Estim. Cost |
|-----------|---|---------|---|--------------|
| | Site Conditions General Site Conditions | rtuting | Commenta/Conscrib | Lotini. Goot |
| | Overall site size. | 5 | Good size. | |
| 1.1.2 | Outdoor athletic areas. | 5 | Adequate for needs. | |
| 1.1.3 | Outdoor playground areas, including condition of equipment and base. | 3 | Good older equipment. Needs absorptive base, which is being done. New equipment will be needed in five years. | \$20,000.00 |
| 1.1.4 | Site landscaping. | 5 | Adequate landscaping. | |
| 1.1.5 | Site accessories (i.e., perimeter and other fencing, guard rails, bike stands, flag poles). | 5 | Adequate | |
| 1.1.6 | Surface drainage conditions (i.e., drains away from building, signs of ponding). | 5 | Good drainage around and away from school. Sandy soils. | |
| 1.1.7 | Evidence of sub-soil problems. | 5 | Sandy soil, no movement. | |
| 1.1.8 | Safety and security concerns due to site conditions. | 4 | No significant issues. | |
| Other | | 3 | Underground fuel storage tank to be removed. | \$10,000.00 |
| | | | | |
| 1.2 | Access/Drop-Off Areas/Roadways/Bus Lanes | | | |

| Section 1 | Site Conditions | Rating | Comments/Concerns | Estim. Cost |
|-----------|--|--------|---|-------------|
| 1.2.1 | Vehicular and pedestrian access points (i.e., size, number, visibility, safety). | 5 | Good access, visibility and safety. | |
| 1.2.2 | Surfacing of on-site road network (note whether asphalt or gravel). | 4 | Gravel roads in very rough condition. There were intended to be paved but never done. | |
| 1.2.3 | Bus lanes/drop-off areas (note whether on-site or off-site). | 5 | On-site bus lane, asphalt. | |
| 1.2.4 | Fire vehicle access. | 5 | Good access all around. | |
| 1.2.5 | Signage. | 5 | Adequate | |
| Other | | | | |
| | | | | |
| 1.3 | Parking Lots and Sidewalks | | | |

| Section 1 | Site Conditions | Rating | Comments/Concerns | Estim. Cost |
|-----------|--|--------|---|-------------|
| 1.3.1 | Number of parking spaces for staff, students and visitors (including stalls for disabled persons). | 4 | Generally adequate for present staff level. | • |
| 1.3.2 | Layout and safety of parking lots. | 4 | Adequate layout, a bit tight. | |
| 1.3.3 | Surfacing and drainage of parking lots (note whether asphalt or gravel). | 5 | Asphalt lot, well drained. | |
| 1.3.4 | Layout and safety of sidewalks. | 4 | Good layout. | |
| 1.3.5 | Surfacing and drainage of sidewalks (note type of material). | 4 | Concrete sidewalks, in good condition. | |
| 1.3.6 | Curb cuts and ramps for barrier free access. | 4 | Adequate | |
| Other | | | | |
| | | - | | |
| | Overall Site Conditions & Estimated Costs | 4 | | \$30,000.00 |

Hillcrest Community School March 15, 2000

| • | Rating | | Comments/Concerns | Estim. Cost |
|---|--|---|--|---|
| Overall Structure | | Bldg. | <u>Description/Condition</u> | |
| Floor structure and beams (i.e., signs of bending, cracking, heaving, settlement, voids, rust, stains). | 5 | Section | Slab-on-grade in good condition. | |
| Vall structure and columns (i.e., signs of bending, cracking, settlement, voids, rust, stains). | 5 | | Bearing concrete block in good condition, no movement evident. | |
| Roof structure (i.e., signs of bending, cracking, voids, ust, stains). | 5 | | Steel structure OWS Joists and metal deck. | |
| | | | | |
| N = N N N N N N N N N | Verall Structure Cloor structure and beams (i.e., signs of bending, racking, heaving, settlement, voids, rust, stains). Vall structure and columns (i.e., signs of bending, racking, settlement, voids, rust, stains). | Overall Structure Cloor structure and beams (i.e., signs of bending, racking, heaving, settlement, voids, rust, stains). Vall structure and columns (i.e., signs of bending, racking, settlement, voids, rust, stains). 5 Cloof structure (i.e., signs of bending, cracking, voids, 5 | Diverall Structure Cloor structure and beams (i.e., signs of bending, racking, heaving, settlement, voids, rust, stains). Wall structure and columns (i.e., signs of bending, racking, settlement, voids, rust, stains). | Averal Structure Idoor structure and beams (i.e., signs of bending, racking, heaving, settlement, voids, rust, stains). Wall structure and columns (i.e., signs of bending, racking, settlement, voids, rust, stains). Bidg. Section Slab-on-grade in good condition. Bearing concrete block in good condition, no movement evident. Bearing concrete block in good condition, no movement evident. Steel structure OWS Joists and metal deck. |

Hillcrest Community School March 15, 2000

| Section 2 | Building Exterior | Rating | | Comments/Concerns | Estim. Cost |
|-----------|--|--------|---|---|-------------|
| 2.2.1 | Roofing and Skylights Identify the availability of an up-to-date inspection report or roofing program. Note if roof sections are of different ages and/or in varying states of Based on the inspection report (and to the extent possible, direct observation), assess and rate roof conditions and estimate costs for required improvements (i.e., covering materials, membrane, insulation, other components). | 3 | Bldg. Section or Roof <u>Section</u> | Description/Condition/Age Built-up roof. Roof repaired in the summer of 1999. Expect on-going repairs as roof keeps blistering. | \$30,000.00 |
| | Roof accessories (i.e., ladders, stairs, hatches, masts, exhaust hoods, chimneys, gutters, downspouts, splashpads). Control of ice and snow falling from roof. | 5 | | Accessories in good condition. N/A | |
| | Skylights (i.e., signs of distress, leaks, ice build-up, condensation, deteriorated materials/seals). | 3 | | Computer room and library, minor condensation evident. On-going repainting of ceiling. Replace skylights with clerestorey roof and windows. | \$50,000.00 |
| Other 2.3 | Exterior Walls/Building Envelope | | Bldg. Section | Description/Condition | |

Hillcrest Community School March 15, 2000

| Section 2 Building Exterior | Rating | | Comments/Concerns | Estim. Cost |
|---|--------|---------------------------------------|---|-------------|
| 2.3.1 Exterior wall finishes (i.e., signs of deterioration, cracks, brick spalling, effluorescence, water stains). | 4 | Brick and m | netal cladding in good condition. | |
| 2.3.2 Fascias, soffits, parapets (i.e., signs of looseness, stains, rust, peeling paint). | 4 | Wood fascia | a and soffit details at entrances, in good condition. | |
| 2.3.3 Building envelope (i.e., evidence of air infiltration/ exfiltration through the exterior wall or ice build up o wall, eaves, canopy). | 5 | No problem | s evident. | |
| 2.3.4 Interface of roof drainage and ground drainage systems. | 4 | Adequate | | |
| 2.3.5 Inside faces of exterior walls (i.e., signs of cracks, water stains, dust spots). | 4 | Minor conde | ensation damage usually due to high humidity. | |
| Other | | | | |
| | | | | |
| 2.4 Exterior Doors and Windows | | Bldg. <u>Description/C</u> Section | <u>Condition</u> | |

Hillcrest Community School March 15, 2000

| | Building Exterior | Rating | Comments/Concerns | Estim. Cost |
|-------|---|--------|--|--------------|
| | Doors (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure). | 5 | Wood doors, new metal frames and hardware. | |
| 2.4.2 | Door accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices). | 5 | Good | |
| 2.4.3 | Exit door hardware (i.e., safety and/or code concerns). | 5 | Excellent | |
| | Windows (i.e., signs of deterioration, rusting metal, glass cracks, peeling paint, damaged seals, sealed unit failure). | 3 | Aluminum windows, all fixed. Operable windows would be preferable. Replace selected windows. | \$40,000.00 |
| 2.4.5 | Window accessories (i.e., latches, hardware, screens, locks, alarms, holders, closers, security devices). | | N/A | |
| 2.4.6 | Building envelope (i.e., signs of heavy condensation on doors or windows). | 5 | All in good condition. No problems evident. | |
| Other | | | | |
| | | | | |
| | Overall Bldg Exterior Condition & Estim Costs | 4 | | \$120,000.00 |

Hillcrest Community School March 15, 2000

| Section 3 | Building Interior - Overall Conditions | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|-------------------------|--|-------------|
| 3.1 | Interior Structure | | Bldg. | <u>Description/Condition</u> | |
| 3.1.1 | Interior walls and partitions (i.e., signs of cracks, spalling, paint peeling). | 5 | Section | Block and frame walls, no movement evident. | |
| 3.1.2 | Floors (i.e., signs of cracks, heaving, settlement). | 5 | | Slab-on-grade, no movement evident. | |
| Other | | | | | |
| | | | | | |
| 3.2 | Materials and Finishes | | Bldg. | <u>Description/Condition</u> | |
| 3.2.1 | Floor materials and finishes. | 3 | | Carpet in classrooms and library. Some carpet requires replacement. Vinyl flooring with opening seams. Quarry tile at vestibule and main entry; recessed grilles. Hardwood gym floor requires refinishing. | \$40,000.00 |
| 3.2.2 | Wall materials and finishes. | 5 | | Vinyl covered gypsum wall board in classrooms. Desco painted concrete block in corridors. Painted block interior walls. Exposed brick feature walls. | |
| 3.2.3 | Ceiling materials and finishes. | 5 | | Stippled ceiling with wood trim in library. T-bar ceiling with recessed lighting in selected areas. Surface mounted lighting in classrooms. | |
| 3.2 | Materials and Finishes (cont'd) | | Bldg. <u>Section</u> | <u>Description/Condition</u> | |

Hillcrest Community School March 15, 2000

| Section 3 Building Interior - Overall Conditions | Rating | Comments/Concerns | Estim. Cost |
|--|--------|--|-------------|
| 3.2.4 Interior doors and hardware. | 5 | Wood doors with pressed steel frames and good hardware. Rolling grilles at food service. | |
| 3.2.5 Millwork | 5 | Plastic laminate tops, doors and drawers. Well laid out and designed. | |
| 3.2.6 Fixed/wall mounted equipment (i.e., writing boar tackboards, display boards, signs). | ds, 5 | Whiteboards, chalkboards and tackboards in good condition. | |
| 3.2.7 Any other fixed/mounted specialty items (i.e., CT equipment, gymnasium equipment). | rs 5 | Gym equipment. | |
| 3.2.8 Washroom materials and finishes. | 5 | Quarry tile floor, full height ceramic tile walls, metal toilet partitions and plastic laminate countertops. | |
| Other | | | |
| 3.3 Health and Safety Concerns Intent is to | | Bldg. <u>Description/Condition</u> | |
| identify renovations considered necessary to | · | Section | |

| Section 3 | Building Interior - Overall Conditions | Rating | Comments/Concerns | Estim. Cost |
|-----------|--|--------|----------------------|-------------|
| | meet applicable codes, primarily due to safety concerns. Basis of evaluation should be an up-to-date inspection report from the authority having jurisdiction together with direct observations as appropriate. Evaluator should note if in his opinion a comprehensive code evaluation is | 5 | No problems evident. | |
| 3.3.1 | Building construction type - combustible or non-combustible, sprinklered or non-sprinklered. | 5 | Non-combustible. | |
| 3.3.2 | Fire separations (i.e., between buildings, wings, zones if non-sprinklered). | 5 | Good | |
| 3.3.3 | Fire resistance rating of materials (i.e., corridor walls and doors). | 5 | Good | |
| 3.3.4 | Exiting distances and access to exits. | 5 | Good | |
| 3.3.5 | Barrier-free access. | 5 | Good | |
| | Availability of hazardous materials audit (i.e., evidence of safety concerns with respect to asbestos, PCB's, chemicals). | | N/A | |
| 3.3.7 | Other health and safety concerns (i.e., evidence of excessive noise conditions, air quality problems) | | N/A | |
| Other | | | | |
| | Overall Bldg Interior Condition & Estim Costs | 5 | | \$40,000.00 |

| | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-------|---|--------|---------|---|-------------|
| 4.1 | Mechanical Site Services | | | | |
| 4.1.1 | Site drainage systems (i.e., surface and underground systems, catch basins). | 4 | 1984 | Surface drainage. No problems reported. Site snow covered at time of inspection. | |
| 4.1.2 | Exterior plumbing systems (i.e., irrigation systems, hose bibs). | 4 | 1984 | Non-freeze hose bibbs installed. | |
| 4.1.3 | Outside storage tanks. | | | | |
| Other | | FI | 1984 | Existing underground diesel storage tank no longer in operation. | |
| 42 | Fire Suppression Systems | | Bldg. | Description/Condition | 1 |
| | The Supplemental Systems | | Section | - Contraction - | |
| 4.2.1 | Fire hydrants and siamese connections. | FI | | Fire hydrant installed at front of building appears to be connected to water storage cistern (not pressurized). | |
| 4.2.2 | Fire suppression systems (i.e., pumps, sprinklers, piping, reservoirs, hoses, stand pipes, CO2 systems). | | 1984 | Building is not sprinklered. | |
| 4.2.3 | Hand extinguishers, blankets and showers (i.e., in CTS areas). | 4 | 1984 | Portable hand extinguishers located throughout. | |
| 4.2.4 | Other special situations (e.g., flammable storage areas, science labs, CTS areas). | | 1984 | N/A | |
| Other | | | | | |
| 43 | Water Supply and Plumbing Systems | | Bldg. | Description/Condition | |
| -1.0 | Trace Supply and Flambing Systems | | Section | <u> </u> | |
| 4.3.1 | Domestic water supply (i.e., pressure, volume, quality - note whether municipal or well supply). | FI | | Underground water storage cistern supplied by "trucked" water. No on-site well. | |
| 4.3.2 | Water treatment system(s). | 4 | 1984 | No problems reported. | |
| 4.3.3 | Pumps and valves (including backflow prevention valves). | 4 | 1984 | Domestic water pressure tanks and pumps. No problems noted. | |
| 4.3.4 | Piping and fittings. | 4 | 1984 | Domestic water piping is copper. | |
| 4.3.5 | Plumbing fixtures (i.e., toilets, urinals, sinks) | 4 | 1984 | Plumbing fixtures generally in good condition. | |
| 4.3.6 | Domestic hot water system (i.e., heater, storage tanks, failure alarms, pressure, volume, recirculation). | 4 | 1984 | Two gas fired domestic water heaters, storage tank and recirculation pump installed. | |
| 4.3.7 | Sanitary and storm sewers, including sumps and pits (note whether sewage system is municipal or septic). | 4 | 1984 | Sanitary sewer is connected to a sewage lift station which discharges to a sewage lagoon. | |
| | | l | l | | |

| Section 4 | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|-----------|---|--------|------------------|--|-------------|
| Othe | er . | | | | |
| | | | | | |
| 4. | 4 Heating Systems | | Bldg. | Description/Condition | |
| | Heating capacity and reliability (including backup | 4 | Section | Two hot water heating boilers. Two in-line heating circulation pumps. | |
| | capacity). | - | All | Two not water reading boilers. Two irrine reading circulation pumps. | |
| | | | | | |
| 4.4. | 2 Heating controls (including use of current energy | 4 | All | Electronic control systems. No D.D.C. | |
| | management technology. | | | | |
| | | | | | |
| 4.4. | 3 Fresh air for combustion and condition of the combustion chimney. | 4 | All | Combustion air and heater installed. | |
| | compasion criminey. | | | | |
| | | | | | |
| 4.4. | Treatment of water used in heating systems. | 4 | All | Chemical pot feeder installed. | |
| | | | | | |
| ļ ,, | | | | | |
| 4.4. | 5 Low water cutoff/pressure relief valves and failure alarms (i.e., hot water heating). | 4 | All | Equipment installed. | |
| | | | | | |
| 4.4. | 6 Heating air filtration systems and filters. | | All | N/A | |
| | | | | | |
| | | | | | |
| 4.4. | 7 Heating humidification systems and components. | | All | N/A | |
| | | | | | |
| | | | | | |
| | 4 Heating Systems (cont'd) | | Bldg. Section | | |
| 4.4. | B Heating distribution systems (i.e., piping, ductwork) and associated components (i.e., diffusers, radiators). | 4 | All | Total of three central air handling units with supply fan, heating coil, evaporative humidifier, filters and mixing box sections. Separate return fans provided. | |
| | | | | | |
| 4.4. | Heating piping, valve and/or duct insulation. | 4 | All | No problems reported. | |
| | | | | | |
| | | | | | |
| 4.4.1 | 0 Heat exchangers. | 4 | All | No problems reported. | |
| | | | | | |
| 441 | 1 Heating mixing haves, dampers and linkages | , | A.II | No applicant annual of | |
| 4.4.1 | Heating mixing boxes, dampers and linkages. | 4 | All | No problems reported. | |
| | | | | | |
| 4.4.1 | 2 Heating distribution/circulation in larger spaces (i.e., user | 4 | All | No problems reported. | |
| | comfort, temperature of outside wall surfaces). | | | | |
| | | | | | |
| | • | | | | |

| Section 4 | Mechanical Systems | Rating | 1 | Comments/Concerns | Estim. Cost |
|-----------|--|--------|------------------|--|-------------|
| 4.4.13 | Zone/unit heaters and controls. | 4 | All | Kiln exhaust hood installed. | • |
| | | | | | |
| | | | | | |
| Other | | | | | |
| | | | | | |
| | | | | | |
| 4.5 | Ventilation Systems | | Bldg. | Description/Condition | |
| | Air handling units capacity and condition. | 4 | Section | | |
| 4.5.1 | All handling drits capacity and condition. | 4 | All | Total of three central air handling units with supply fan, heating coil, evaporative humidifier, filters and mixing box sections. Separate return fans provided. | |
| | | | | | |
| 452 | Outside air for the occupant load (if possible, reference | 4 | A.II | No sould not seemed | |
| 4.5.2 | CFM/occupant). | 4 | All | No problems reported. | |
| | | | | | |
| 453 | Air distribution system (if possible, reference number of | 4 | A.II | No problems reported | |
| 4.5.5 | air changes/hour). | 4 | All | No problems reported. | |
| | | | | | |
| 4.5.4 | Exhaust systems capacity and condition. | 4 | All | No problems reported. | |
| | | 7 | All | No problems reported. | |
| | | | | | |
| 4.5.5 | Separation of out flow from air intakes. | 4 | All | No problems reported. | |
| | | _ | / | no prosionio reported. | |
| | | | | | |
| 4.5.6 | Special/dedicated ventilation and/or exhaust systems | 4 | All | Kiln exhaust hood installed. | |
| | (i.e., kitchen, labs, CTS areas). | - | / | TAIL CANADA NOOD INSTANCE. | |
| | | | | | |
| Other | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 4.5 | Ventilation Systems (cont'd) | | Bldg. Section | Description/Condition | |
| | Note: Only complete the following items if there are separate ventilation and heating systems. | | | | |
| 4.5.7 | Ventilation controls (including use of current energy management technology). | 4 | All | Electronic control systems. No D.D.C. | |
| | | | | | |
| | | | | | |
| 4.5.8 | Air filtration systems and filters. | 4 | All | Disposable filter media. | |
| | | | | | |
| | | | | | |
| 4.5.9 | Humidification system and components. | 4 | All | Evaporative humidifier sections in air handlers. | |
| | | | | | |
| | | | | | |
| | | | | | |

| | Mechanical Systems | Rating | | Comments/Concerns | Estim. Cost |
|--------|---|--------|---------|---------------------------------------|-------------|
| 4.5.10 | Heat exchangers. | | All | N/A | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 4.5.11 | Ventilation distribution system and components (i.e., ductwork, diffusers, mixing boxes, dampers, linkages). | 4 | All | No major problems noted. | |
| | assimoni, amassis, mixing boxes, aampers, iimages). | | | | |
| | | | | | |
| | | | | | |
| Other | | | | | |
| Other | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 46 | Cooling Systems | | Bldg. | Description/Condition | 1 |
| 4.0 | occurry dystems | | Section | | |
| 4.6.1 | Cooling system capacity and condition (i.e., chillers, | | All | N/A | |
| | cooling towers, condensers). | | | | |
| | | | | | |
| | | | | | |
| 4.6.2 | Cooling distribution system and components (i.e., | | All | N/A | |
| | ductwork, diffusers, mixing boxes, dampers, linkages) | | | | |
| | | | | | |
| | | | | | |
| 4.6.3 | Cooling system controls (including use of current energy | | All | N/A | |
| | management technology). | | | | |
| | | | | | |
| | | | | | |
| 4.6.4 | Special/dedicated cooling systems (i.e., labs, CTS areas). | | All | N/A | |
| | areas). | | | | |
| | | | | | |
| | | | | | |
| Other | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | ĺ | l | | |
| 4.7 | Building Control Systems | | Bldg. | Description/Condition | |
| | L | | Section | | |
| 4.7.1 | Building wide/system wide control systems and/or energy management systems. | 4 | All | Electronic control systems. No D.D.C. | |
| | g,gonon oysionis. | | l | | |
| | | | 1 | | |
| | | | l | | |
| | | | l | | |
| | | ĺ | l | | |
| | | | 1 | | |
| | | ĺ | l | | |
| | Overall Mech Systems Condition & Estim. Costs | 4 | | | 0 |

Section 5 Electrical Systems
5.1 Site Services

Other

5.2 Life Safety Systems

condition).

condition).

Other

5.1.1 Primary service capacity and reliability (i.e., access, location, components, installation, bus sizes - note

5.1.2 Site and building exterior lighting (i.e., safety concerns

5.1.3 Vehicle plug-ins (i.e., number, capacity, condition).

5.2.1 Fire and smoke alarm systems (i.e., safety concerns, to-date technology, regularly tested).

5.2.2 Emergency lighting systems (i.e., safety concerns,

5.2.3 Exit lighting and signage (i.e., safety concerns,

5.3 Power Supply and Distribution5.3.1 Power service surge protection.

5.3.2 Panels and wireways capacity and condition.

whether overhead or underground).

School Facility Evaluation Project Part II - Physical Condition

| | Rating | Comments/Concerns | Estim. Cost |
|--------|--------|---|-------------|
| | 4 | Power supplied underground from Alberta Power polemounted transformer. Service size 600 ampere, 120/208 volt 3 P, 4 W demand 220 amperes. Main switchgear manufactured by Square D in acceptable condition with spare capacity to meet current and future requirements. | |
| ns). | 4 | HID surface mounted luminaires at building exits and entrances in fair condition. Parking and playground areas illuminated with HID streetlighting luminaires on steel poles. | |
| | 4 | 30 vehicle plug-ins provided on steel standalone posts. All equipment is in good condition. | |
| s, up- | 3 | Bldg. Section Description/Condition Electrovox 2001 multi- zone system, equipment is obsolete and not expandable. No visual signal appliances. Annual testing completed on Aug 9, 1999. | \$12,000.00 |
| | 5 | Designated emergency lighting luminaires are supplied from the emergency generator. | |
| | 4 | Incandescent Exit signage provided at all exits meets code requirements. | |
| | | Bldg. Section Description/Condition | |
| | 2 | None | \$ 2,000.00 |

Branch circuit wiring is supplied by Square D panelboards located in the

classroom areas.

electrical/generator room, janitor's room, mechanical room, corridors and office. All panelboards and wireways are in acceptable condition, but are generally full in

| | Electrical Systems | Rating | Comments/Concerns | Estim. Cost |
|-------|---|--------|---|-------------|
| 5.3.3 | Emergency generator capacity and condition and/or UPS (if applicable). | 4 | A diesel fired Simpower 31 kw emergency generator is located in a separate electrical/generator room provides power to run designated mechanical and lighting loads. Unit incorporates automatic transfer capability. | |
| 5.3.4 | General wiring devices and methods. | 4 | All wiring devices are specification grade with stainless steel cover plates. Wiring is copper with RW-90 insulation. | |
| 5.3.5 | Motor controls. | 4 | Individual Klockner Moeller magnetic and manual motor starters are mounted on splitter troughs. All equipment is in good condition. | |
| Other | | | | |
| 5.4 | Lighting Systems | | Bldg. | |
| 5.4.1 | Interior lighting systems and components (i.e., illumination levels, conditions, controls). | 4 | Lighting is generally fluorescent, surface mounted 1x4 2 lamp luminaires with Holophane 6100 series lens in the classrooms, recessed 1 lamp 1 x 4s in the corridors, surface mounted strip lights withe wire guards on the gymnasium, T12 40 watt lamps, electromagnetic ballasts Classroom and administration areas 550 - 800 lux Gymnasium 300 lux. | |
| 5.4.2 | Replacement of ballasts (i.e., health and safety concerns). | 4 | Replacement on failure, no PCB Ballasts reported or noted. | |

| Section 5 | Electrical Systems | Rating | Comments/Concerns | Estim. Cost |
|----------------|--|--------|--|-------------|
| 5.4.3 Other | Implementation of energy efficiency measures and recommendations. | 3 | The district is reviewing a proposal by Johnson Controls to complete an energy retrofit of the lighting and control systems. No program is currently in place. | \$20,000.00 |
| | | | | |
| 5.5 | Network and Communication Systems | | Bldg. | |
| 5.5.1 | Telephone system and components (i.e., capacity, reliability, condition). | 4 | Section Description/Condition Trillium 3 line telephone system. | |
| 5.5.2 | Other communication systems (i.e., public address, intercom, CCTV, satellite or cable TV). | 4 | Hardwired TOA system with master station in the general office. No tiein to telephone system. | |
| 5.5.3 | Network cabling (if available, should be category 5 or better). | 4 | Data cabling run to all classrooms and administration areas to Category 5 requirements. | |
| 5.5.4 | Network cabling installation (i.e., in conduit, secured to walls or tables). | 4 | Cable run in conduit and surface raceway systems in walls and some ceiling areas, some cable run free air in ceilings | |
| 5.5.5 | Wiring and telecommunication closets (i.e., size, security, ventilation/cooling, capacity for growth). | 4 | Patch panel located in Audio Visual Storage room | |
| 5.5.6 | Provision for dedicated circuits for network equipment (i.e., hubs, switches, computers). | 3 | Classrooms provided with adequate outlets to meet current requirements but no future expansion capability for more than I terminal per classroom. Computer lab area has sufficient dedicated circuits. | \$10,000.00 |

| Section 5 | Electrical Systems | Rating | Comments/Concerns | Estim. Cost |
|-----------|--|--------|---|-------------|
| Other | | | | |
| | | | | |
| | | | | |
| | | | | <u> </u> |
| | Miscellaneous Systems | | Bldg. Section Description/Condition | |
| 5.6.1 | Site and building surveillance system (if applicable). | | None | |
| | | | | |
| 5.6.2 | Intrusion alarms (if applicable). | 4 | School District standard ITI "Caretaker" system. | |
| 0.0.2 | militation diamio (ii applicable). | 4 | School district standard TTT Caretaker System. | |
| | | | | |
| 5.6.3 | Master clock system (if applicable). | 4 | There is no master clock system, all clocks are battery operated. | |
| | | | | |
| | | | | |
| Other | | | | |
| | | | | |
| 5.7 | Elevators/Disabled Lifts (If applicable) | | | 1 |
| 5.7.1 | Elevator/lift size, access and operating features (i.e., | | | |
| | sensing devices, buttons, phones, detectors). | | | |
| | | | | |
| 5.7.2 | Condition of elevators/lifts. | | | |
| | | | | |
| 573 | Lighting and ventilation of elevators/lifts. | | | |
| | | | | |
| | | | | |
| Other | | | | |
| | | | | |
| | | | | |
| | Overall Elect. Systems Condition & Estim Costs | 4 | | \$44,000.00 |

| Section 6 | Portable Buildings | Rating | Comments/Concerns | Estim. Cost |
|-----------|--|--------|---|------------------|
| | Note: Separate sheets can be completed, if necessary, for portable buildings of different ages and/or conditions. | | | |
| 6.1.1 | Foundation and structure (i.e., signs of bending, cracking, settlement, rust, voids, stains). | 4 | Wood structure. | |
| 6.1.2 | Roof materials and components (i.e., signs of deterioration, leaks, ice build-up). | 4 | BUR; metal flashing. | |
| 6.1.3 | Exterior wall finishes (i.e., signs of deterioration, cracks, water stains). | 4 | Stucco | |
| 6.1.4 | Doors and windows (i.e., signs of deterioration, rusting hardware, glass cracks, peeling paint, damaged seals). | 4 | Vertical steel sliders, some taped shut. | |
| 6.1.5 | Interior finishes (i.e., floors, walls, ceiling). | 4 | Vinyl covered gypsum wall board, carpet floor (new). | |
| 6.1.6 | Millwork (i.e., counters, shelving, vanities, cabinets). | | | |
| 6.1.7 | Fixed/wall mounted equipment (i.e., writing boards, tackboards, display boards, signs) | | | |
| 6.1.8 | Heating system. | 2 | The two 1986 portables have older furnaces which are in poor condition. | \$30,000.00 |
| 6.1.9 | Ventilation system. | 2 | See 6.1.8. | Costed in 6.1.8. |
| 6.1.10 | Electrical, communication and data network systems. | 4 | Power is supplied by a single 100 ampere panel. Fire alarm, emergency lighting, communication systems, data cabling, and exit signage have been extended from the main school building. Lighting is provided by surface mounted 1x4 luminaires with wraparound lens, lighting levels average 600 lux in the classrooms and 220 lux in the corridors | |
| 6.1.11 | Health and safety concerns (i.e., fire and smoke alarms, fire protection systems, exiting, fire resistance rating of materials). | | N/A | |
| 6.1.12 | Barrier-free access. | | | |
| - | Overall Portable Bldgs Condition & Estim Costs | 4 | | \$30,000.00 |

| | Space Adequacy | This Facility | | | Equiv. New Facility | | | Surplus/ | | |
|-----------|--|---------------|----------|------------|---------------------|------|------------|------------|---|--|
| Section 7 | | No. | Size | Total Area | No. | Size | Total Area | Deficiency | Comments/Concerns | |
| 7.1 | Classrooms | 6 | <u> </u> | 423.3 | 6 | 80 | 480 | -56.7 | Classrooms are somewhat small, but adequate given the | |
| | Portables | 2 | 72 | 144 | 2 | 70 | 140 | 4 | emall class sizes | |
| 7.2 | Science Rooms/Labs | 1 | 92.64 | 92.64 | 0 | 0 | 0 | 92.64 | | |
| 7.3 | Ancillary Areas (i.e., Art, Computer Labs, Drama, Music,) | 1 | 203.5 | 203.51 | 3 | | 310 | -106.5 | Combined art/science room. | |
| 7.4 | Gymnasium (incl. gym storage) | 1 | 426.9 | 426.94 | 1 | 430 | 430 | -3.1 | Gym is well suited to school needs. | |
| | Storage | 2 | | 38.22 | 1 | 31 | 31 | 7.2 | | |
| | Change Rooms/Office Area | 3 | | 85.66 | 3 | | 65 | 20.7 | | |
| 7.5 | Library/Resource Areas | 1 | 137.1 | 137.06 | 1 | 127 | 127 | 10.1 | | |
| 7.6 | Administration/Staff, Physical Education, Storage Areas | 10 | | 173.19 | 11 | | 207 | -33.8 | Sufficient space for present staff. | |
| 7.7 | CTS Areas 7.7.1 Business Education | | | | | | | | | |
| | 7.7.2 Home Economics | | | | | | | | | |
| | 7.7.3 Industrial Arts | | | | | | | | | |
| | 7.7.4 Other CTS Programs | | | | | | | | | |
| 7.8 | Other Non-Instructional Areas (i.e., circulation, wall area, crush space, wc area) | | | 718.16 | | | 719.8 | -1.6 | | |
| | Overall Space Adequacy Assessment | | | 2442.68 | | | 2509.8 | -67.1 | Overall, the school size is comfortable for the present and projected enrollment. | |

| Evaluation Component/ Sub-Component | Additional Notes and Comments |
|--|-------------------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

School Facility Evaluation Project Part II - Physical Condition

Hillcrest Community School March 15, 2000

| Evaluation Component/ Sub-Component | | Additional Notes and Comments |
|-------------------------------------|--|-------------------------------|
| | | |
| | | |
| | | |

Alberta Infrastructure


School Facilities Branch
















| | FORT VERMILLION SCH. DIV. NO. 52 | | | | | | |
|------------------|----------------------------------|-----------|-----------------|--|--|--|--|
| | HILL CREST COMMUNITY SCHOOL | | | | | | |
| | SCHOOL BUILDINGS SERVICES | | | | | | |
| | DATE : 85-01-03 | | PLT. ID :017748 | | | | |
| REVISED 98-01-30 | DWN. BY: A.W. | SITE PLAN | CODE: 1712 | | | | |
| | SCALE: 1500 | • | SHEET: 1 of 3 | | | | |